

55

Al Jazirah Vehicles		Location		9 Jun DATE		DOT	Tread Depth	P	Spec	Clp	R	Comments
Jeddah		Howard Riley		Service Manager		Contacts						
KM 30K	VIN [REDACTED]	Tire Code RF	VN245	11 11 10	30	ST358J	C1	N				
		Tire Code LF	W2108	13 13 13	31	ST369J	C0	N	Tire appears new			
		Tire Code RR	VN235	10 5 10 5 10	31	ST358J	C1	N	Light side wall cut and deep cut in tread area			
		Tire Code LR	VN245	10 10 10	33	ST358J	C2	N	H Riley driving unit Bruce took photos, needs new RR tire			
KM 58K	VIN [REDACTED]	Tire Code RF	W2188	12 13 11 5	37	ST369J	C2	N	Do not appear original, photo of cuts 7/32 deep taken			
		Tire Code LF	W2457	11 13 12	37	ST369J	C1	N				
		Tire Code RR	VN228	12 11 11	38	ST369J	C1	N				
		Tire Code LR	VN347	11 10 11	38	ST369J	C2	N	Nail found in tire it was pulled and was not leaking			
KM 25K	VIN [REDACTED]	Tire Code RF	W2477	11 10 10	38	ST369J	C0	Y	Cord plug in tire			
		Tire Code LF	W2477	10 11 11 5	29	ST369J	C1	N				
		Tire Code RR	W2477	10 10 10	28	ST369J	C1	Y	Large cord plug			
		Tire Code LR	W2477	10 10 11	28	ST369J	C0	N	Looks like city driving			
KM 46K	VIN [REDACTED] New Goodyear tires on vehicle	Tire Code RF			28				Goodyear Wrangler RT/S			
		Tire Code LF			29				P255/70R16 109S			
		Tire Code RR			28				Only checked infl pressure			
		Tire Code LR			28				Also new shocks on vehicle.			
KM 118K	VIN [REDACTED]	Tire Code RF	VN368	14 13 12	26	ST369J	C0	N				
		Tire Code LF	VN398	13 12 13	26	ST369J	C0	N				
		Tire Code RR	VN106	10 10 9	28	ST369J	C1	Y	Cord plug in tire			
		Tire Code LR	VN508	13 5 13 13	38	DE504J	C0	N	Special Service tire -DE504J			
KM 107K	VIN [REDACTED]	Tire Code RF	VN358	12 12 11 5	39	ST369J		N				
		Tire Code LF	VN358	12 11 5 11 5	40	ST369J		N				
		Tire Code RR	VN357	10 8 8 5	40	ST369J		N				
		Tire Code LR	VN377	9 8 8	38	ST369J		N	Very little off road driving, new front tires on unit			
KM 41K	VIN [REDACTED]	Tire Code RF	W2086	10 5 10 10	35	ST369J	C1	N				
		Tire Code LF	W2096	9 8 5 8 5	36	ST369J	C1	N				
		Tire Code RR	W2096	10 9 9	35	ST369J	C1	N				
		Tire Code LR	W2096	10 9 9	28	ST369J	C1	N	Found cut to steel w/ slow leak tire has evidence of tread separation This tire was cut open and photos taken, tire sample is with Ritz at HHA			
KM 16K	VIN [REDACTED]	Tire Code RF	VN116	9 8 7 5	34	ST369J	C1	N				
		Tire Code LF	VN116	9 8 8	34	ST369J	C1	Y	Small nail in tire & one cord repair			
		Tire Code RR	VN116	9 8 5 8	33	ST369J	C1	Y	Cord repair			
		Tire Code LR	VN116	8 8 8	32	ST369J	C1	N	Side wall has slice in it			

DOT Outside / Middle / Inside

REDACTED









67 vehicles 268 tires on vehicles inspected 5 tires showing loose tread  
Clp codes C0, C1, C2, C3

KM 9K	VIN [REDACTED]	Tire Code RF	VN108	12.11.12	23	ST369J	C0	N	Tire has nail in it and is leaking
		Tire Code LF	VN108	12.11.5.12	28	ST369J	C0	N	
		Tire Code RR	VN108	12.11.5.12	26	ST369J	C0	N	
		Tire Code LR	VN108	12.11.5.12	14	ST369J	C0	N	
KM 94K	VIN [REDACTED]	Tire Code RF	VN347	9.5.8.6	38	ST369J	C1	N	Cord repair P255/70R16 109S P255/70R16 109S
		Tire Code LF	W2097	8.5.5	39	ST369J	C1	Y	
		Tire Code RR	GY	Wrangler	40	RT/S			
		Tire Code LR	GY	Wrangler	38	RT/S			
KM 27K	VIN Vehicle on lift with door locked, and transmission jack under vehicle	Tire Code RF	VN346	9.8.8	26	ST369J	C1	N	Cord repair Cord repair and large cut on lug
		Tire Code LF	VN346	10.10.10	25	ST369J	C1	N	
		Tire Code RR	VN346	8.5.8.5.8.5	33	ST369J	C0	Y	
		Tire Code LR	VN346	9.8.5.8.5	29	ST369J	C2	Y	

REDACTED

Hajj Hussein Alweza Jeddah		Location		Ali Alweza						
Ritz Pisano Service Mgr Danny Hinchin Ser Dir		Contacts								
10 Jun		DOT		Tread Depth		P	Spec	Chp	R	Comments
KM 27K	VIN [REDACTED]	Tire Code RF	W2017	10 10 8	36	ST369J	C3	N		
		Tire Code LF	W2017	11 10 11	35	ST369J	C0	N		
		Tire Code RR	W2017	10 9 7	35	ST369J	C1	N		Heavy inner tire wear
		Tire Code LR	W2017	11 10 12	35	ST369J	C1	N		
KM 60K	VIN [REDACTED]	Tire Code RF	VN346	10 9 8	38	ST369J	C3	N		Deep cut in tread
		Tire Code LF	VN029	13 13 13	33	DE504J	C0	N		New Special Service tire
		Tire Code RR	VN346	10 9 8	37	ST369J	C2	N		Some impact damage
		Tire Code LR	VN346	10 10 7 5	37	ST369J	C3	N		
KM 73K	VIN [REDACTED]	Tire Code RF	TOYO	TRANPATH	30					
		Tire Code LF	TOYO	P255/70R16	27					
		Tire Code RR	TOYO	109S	30					
		Tire Code LR	VN368	12 11 12	31	ST369J	C0	N		Don't know why LR was changed from TOYO?
KM 32K	VIN [REDACTED]	Tire Code RF	W2397	11 12 10	34	ST369J	C0	N		
		Tire Code LF	W2397	11 11 10	33	ST369J	C0	N		
		Tire Code RR	W2397	12 10 11	33	ST369J	C0	N		
		Tire Code LR	W2397	12 10 11	33	ST369J	C0	N		Vehicle just serviced & technician did not notice nail & leak in tire
KM 27K	VIN [REDACTED]	Tire Code RF	VN368	12 13 13	34	ST369J	C0	N		
		Tire Code LF	VN368	13 13 13	35	ST369J	C0	N		
		Tire Code RR	VN368	13 13 13	35	ST369J	C0	N		This is a new set of replacement tires
		Tire Code LR	VN368	12 13 12	31	ST369J	C1	Y		Tire has plug in the side wall and is bulging in repair area*****
KM 46K	VIN [REDACTED]	Tire Code RF	VN326	8 7 5	20	ST369J	C1	N		Nail in tire that is leaking
		Tire Code LF	VN326	9 9 6 5	21	ST369J	C2	Y		Cord plug and inside edge is down to steel belts
		Tire Code RR	VN326	10 9 9	20	ST369J	C1	Y		Cord plug
		Tire Code LR	VN326	8 7 8	23	ST369J	C1	Y		Cord plug in tread area and one in shoulder area
										Vehicle needs 4 tires good example of a problem vehicle*****
KM 38K	VIN [REDACTED]	Tire Code RF	VN326	7 7 5	28	ST369J	C1	Y		Cord plug outside tread area
		Tire Code LF	W2107	10 8 6	26	ST369J	C2	N		
		Tire Code RR	VN136	7 6 5 4	25	ST369J	C2	N		Tire worn out
		Tire Code LR	VN326	6 5 6 5	33	ST369J	C3	Y		Cord plug & dangerous cut in tread area

**REDACTED**

Al Jazirah Vehicles Riyadh John Wiese Warranty Manager		Location		 Ahmad Yahya, National Marketing Director Waleed A Al-Hokair, Branch Manager						
KM	VIN	12 Jun DATE	DOT	Tread Depth	P	Spec	Chip	R	Comments	
KM 49K		Tire Code RF	VN106	8.8.8.5		17 ST369J	C1	N	Valve stem leaking from core No valve cap	
		Tire Code LF	VN106	10.9.9		39 ST369J	C2	N		
		Tire Code RR	VN106	8.8.8		38 ST369J	C2	N		
		Tire Code LR	VN106	8.8.8		39 ST369J	C2	N		
KM 6K		Tire Code RF	VN118	13.13.13		27 ST369J	C0	N	(2) Cords in one repair location	
		Tire Code LF	VN118	13.13.13		26 ST369J	C0	N		
		Tire Code RR	VN118	13.13.13		32 ST369J	C0	Y		
		Tire Code LR	VN118	13.13.13		26 ST369J	C0	N		
KM 17K		Tire Code RF	W2148	12.5.12.12		27 ST369J	C1	N	Some off-road use (witness marks)	
		Tire Code LF	W2148	13.13.13		27 ST369J	C0	N		
		Tire Code RR	W2148	12.12.12		29 ST369J	C0	N		
		Tire Code LR	W2148	12.12.12		27 ST369J	C0	N		
KM 79K		Tire Code RF	VN116	9.9.5.9		26 ST369J	C2	Y	One cord repair	
		Tire Code LF	VN116	10.10.10		28 ST369J	C3	N		
		Tire Code RR	VN285	13.12.13		29 ST358J	C0	N		
		Tire Code LR	VN457	13.12.13		28 ST369J	C1	N		
KM 54K		Tire Code RF	VN378	13.13.13		25 ST369J	C0	N	New tires recently	
		Tire Code LF	VN398	13.13.13		15 ST369J	C0	N		
		Tire Code RR	VN388	13.13.13		25 ST369J	C0	N		
		Tire Code LR	VN388	13.13.12.5		25 ST369J	C0	N		
KM 7K		Tire Code RF	VN108	13.13.13		26 ST369J	C0	N	No valve cap	
		Tire Code LF	VN108	13.13.13		27 ST369J	C0	N		
		Tire Code RR	VN108	13.13.13		26 ST369J	C0	N		
		Tire Code LR	VN108	13.13.13		27 ST369J	C0	N		
KM 12K		Tire Code RF	VN487	13.12.13		28 ST369J	C2	N	Fairly new vehicle/tires	
		Tire Code LF	VN487	13.12.13		29 ST369J	C2	N		
		Tire Code RR	VN487	13.13.13		28 ST369J	C0	N		
		Tire Code LR	VN487	13.13.13		28 ST369J	C0	N		

DOT Outside / Middle / Inside

Chip codes C0 C1 C2 C3

**REDACTED**

KM 14K	VIN [REDACTED]	Tire Code RF	VN138	13.13.13	28	ST369J	C0	N	
		Tire Code LF	VN138	13.13.13	28	ST369J	C0	N	
		Tire Code RR	VN138	13.13.13	28	ST369J	C0	N	
		Tire Code LR	VN138	13.13.13	28	ST369J	C0	N	
KM 123K	VIN [REDACTED]	Tire Code RF	W2467	13.13.13	33	ST369J	C0	N	
		Tire Code LF	W2447	11.5.11.5.11	32	ST369J	C2	N	
		Tire Code RR	VN457	13.13.13	33	ST369J	C0	N	
		Tire Code LR	VN467	12.13.12	34	ST369J	C0	N	Some off-road use (witness marks)
KM 8K	VIN [REDACTED]	Tire Code RF	W2107	13.12.5.12	29	ST369J	C0	N	
		Tire Code LF	W2107	13.13.13	30	ST369J	C0	N	
		Tire Code RR	W2107	12.12.12	30	ST369J	C0	N	
		Tire Code LR	W2107	13.12.12	32	ST369J	C0	N	
KM 67K	VIN [REDACTED]	Tire Code RF	VN155	10.11.10	26	ST358J	C2	N	
		Tire Code LF	VN265	10.10.10	45	ST358J	C2	N	
		Tire Code RR	VN265	10.11.10	35	ST358J	C0	N	
		Tire Code LR	VN265	11.11.11	38	ST358J	C0	N	Nail removed from tread lug, no leak
KM ??	VIN [REDACTED]	Tire Code RF	VN457	11.12.12	29	ST369J	C0	N	
		Tire Code LF	VN367	10.10.10	32	ST369J	C2	N	
		Tire Code RR	VN367	10.10.10	39	ST369J	C1	N	
		Tire Code LR	VN457	13.12.12	30	ST369J	C0	N	

REDACTED

Hajj Hussein Alreza Riyadh Jeff Simpson Service Manager		Location						Abdullah Al Rashed, Credit Manager, "Acting General Manager"	
13 Jun		DATE	DOT	Tread Depth	P	Spec	Chip	R	Comments
KM 14K	VIN	Tire Code RF	VN326	11 5, 12 11 5	26		C1	N	
	[REDACTED]	Tire Code LF	VN316	12 11 11 5	35		C0	N	Missing valve cap
	[REDACTED]	Tire Code RR	VN316	11 5 11 5, 11	38		C1	N	
	[REDACTED]	Tire Code LR	VN326	11 5 11 5, 12	37		C1	Y	CUT ON SIDE WALL Unit was in a prior unrelated accident, has a bent frame
KM 20K	VIN	Tire Code RF	W2407	12, 12, 12	28		C0	N	
	[REDACTED]	Tire Code LF	W2407	13, 12, 12	29		C0	N	
	[REDACTED]	Tire Code RR	W2407	12, 12, 12	28		C0	N	
	[REDACTED]	Tire Code LR	W2407	12, 12, 12	29		C0	N	
KM 18K	VIN	Tire Code RF	W2396	12, 12, 12	40		C1	N	
	[REDACTED]	Tire Code LF	W2396	11, 11, 12	35		C1	N	Has nail in tire with slight leak
	[REDACTED]	Tire Code RR	W2396	12, 12, 12	37		C1	Y	Missing valve cap
	[REDACTED]	Tire Code LR	W2396	12, 12, 12	37		C0	N	Missing valve cap
KM 59K	VIN	Tire Code RF	VN326	11, 11, 10 5	29		C1	N	
	[REDACTED]	Tire Code LF	VN326	11 5, 12, 11 5	28		C1	Y	Repair is in shoulder area
	[REDACTED]	Tire Code RR	VN326	11, 11, 11	30		C1	N	Thorn in side wall
	[REDACTED]	Tire Code LR	VN326	11, 11, 11	28		C1	N	
KM 68K	VIN	Tire Code RF	VN488	13, 13, 13	32		C0	N	Special Service tire
	[REDACTED]	Tire Code LF	VN518	13, 13, 13	33		C0	N	Special Service tire
	[REDACTED]	Tire Code RR	VN326	9, 8 5, 7	36		C1	N	
	[REDACTED]	Tire Code LR	VN326	10, 9, 7	35		C1	N	
KM 4K	VIN	Tire Code RF	W2477	12, 13, 13	26		C0	N	
	[REDACTED]	Tire Code LF	W2487	12, 13, 13	27		C0	N	
	[REDACTED]	Tire Code RR	W2477	12 5, 12 5 12	28		C0	N	
	[REDACTED]	Tire Code LR	W2477	11 5, 11 5, 11	30		C0	N	
KM 20K	VIN	Tire Code RF	W2128	12, 13, 12	30		C0	N	
	[REDACTED]	Tire Code LF	W2128	12, 12, 12	30		C0	N	
	[REDACTED]	Tire Code RR	W2128	12, 12, 12	30		C1	N	Has nail with slight leak
	[REDACTED]	Tire Code LR	W2128	12, 12, 12	30		C0	N	

**REDACTED**

DOT Outside / Middle / Inside

Chip codes C0, C1, C2, C3

Al Jazurah Al Khobar		Location						Shk Abdullah Al Kradijees - President Shk Abdullatif A Al-Mubarak, Regional Manager	
Paul Wright Technical Branch Mgr		Contacts							
	VIN	DATE	DOT	Tread Depth	P	Spec	Chp	R	Comments
KM 72K	[REDACTED]	Tire Code RF	VN116	8.5.8.5.7		35 ST369J	C2	N	Starting to sepearate
		Tire Code LF	VN116	9.9.9		35 ST369J	C2	N	Starting to sepearate
		Tire Code RR	VN116	9.9.8		35 ST369J	C2	N	One nail, not leaking
		Tire Code LR	VN116	7.9.8		32 ST369J	C1	N	
KM 48K	[REDACTED]	Tire Code RF	VN235	9.11.11		35 ST358J	C1	Y	Two sepearate rope repairs and sholder cracking
		Tire Code LF	VN235	11.11.10		33 ST358J	C1	N	Sholder Cracking
		Tire Code RR	VN285	11.12.11.5		30 ST358J	C2	N	Has nail and is leaking
		Tire Code LR	VN285	11.12.11		32 ST358J	C2	N	
KM 49K	[REDACTED]	Tire Code RF				34 DE504J			All tires new Special Service
		Tire Code LF				35 DE504J			
		Tire Code RR				34 DE504J			
		Tire Code LR				34 DE504J			
KM 60K	[REDACTED]	Tire Code RF	VN498	13.13.5.13		30 ST369J	C0	N	One nail that's leaking
		Tire Code LF	VN488	13.13.13		31 ST369J	C0	N	
		Tire Code RR	VN228	12.12.12		12 ST369J	C2	N	
		Tire Code LR	VN238	13.12.11.5		29 ST369J	C0	N	

**REDACTED**

DOT Outside / Middle / Inside

Chp codes C0, C1, C2, C3

HHA Al Khobar		Location								Shk Hasan A Abdulhasan, Director / Owner Gary Wager, General Manager	
Steve Freeman Service Manager		Contacts									
15 Jun		DATE	DOT	Tread Depth	P	Spec	Chp	Grk	R	Comments	
KM 111K	VIN [REDACTED]	Tire Code RF	VN348	13,13,13	23	ST369J	C0		N		
		Tire Code LF	VN387	12,12,11	23	ST369J	C1		N		
		Tire Code RR	VN338	12,12,12	23	ST369J	C0		N		
		Tire Code LR	W2167	12,11,5,10	23	ST369J	C0		N		
KM 65K	VIN [REDACTED]	Tire Code RF	VN316	11,5,10,5,9	36	ST369J	C1		N	1 nail in tire with slight leak, one repair, one deep cut to steel cord One Cord Repair and one nail that's not leaking	
		Tire Code LF	VN326	11,11,10,5	38	ST369J	C1		N		
		Tire Code RR	VN326	10,5,10,5,10	34	ST369J	C2	Y	Y		
		Tire Code LR	VN326	11,11,10	40	ST369J	C1		Y		
KM 55K	VIN [REDACTED]	Tire Code RF	W2506	10,10,10	30	ST369J	C1	2	N		
		Tire Code LF	W2506	10,10,9	30	ST369J	C0	1	N		
		Tire Code RR	W2506	9,8,8	28	ST369J	C2	2	N		
		Tire Code LR	W2506	9,9,9	31	ST369J	C0	2	N		
KM 35K	VIN [REDACTED]	Tire Code RF	W2476	10,10,10	30	ST369J	C2	2	N	large eight inch area of tread separation, recommended tires be replaced	
		Tire Code LF	W2067	12,11,10	33	ST369J	C1	3	N		
		Tire Code RR	W2057	11,10,12	30	ST369J	C0	0	N		
		Tire Code LR	VN347	12,12,12	32	ST369J	C0	0	N		
KM 10K	VIN [REDACTED]	Tire Code RF	W2217	12,5,12,12,5	27	ST369J	C0	0	N	One nail in tread, slowly leaking	
		Tire Code LF	W2217	13,12,13	29	ST369J	C0	0	N		
		Tire Code RR	W2217	12,12,13	27	ST369J	C1	2	N	Cut on side wall	
		Tire Code LR	W2217	13,12,5,12,5	28	ST369J	C0	0	N		
KM 28K	VIN [REDACTED]	Tire Code RF	W2456	8,8,8	31	ST369J	C1	1	N		
		Tire Code LF	W2456	8,7,8	31	ST369J	C0	1	N		
		Tire Code RR	W2456	8,8,8	31	ST369J	C2	2	N		
		Tire Code LR	W2456	8,7,7	31	ST369J	C1	2	N		
KM 26K	VIN [REDACTED]	Tire Code RF	W2507	12,11,11	34	ST369J	C0	0	N		
		Tire Code LF	W2507	12,12,13	28	ST369J	C0	0	N		
		Tire Code RR	W2507	11,11,11,5	28	ST369J	C0	0	N		
		Tire Code LR	W2507	12,12,12	28	ST369J	C0	0	N		

**REDACTED**

DOT Outside / Middle / Inside

Chip codes C0, C1, C2, C3

Almana Motors Co  
 Doha, Qatar  
 Boghos K. Kalachian  
 Service Manager

Location

Contacts

*Bader Almana Managing Director*

DATE	DOT	Tread Depth	P	Spec	Chip	Cr	R	Comments	
KM 84K	VIN [REDACTED]	Tire Code RF	VN215	7.7.4	23	ST358J	C3	1 N	Severe side wall scuffing and ROWL tears
		Tire Code LF	VN215	7.7.5	27	ST358J	C3	1 N	
		Tire Code RR	W2345	12.11.12	36	SI878J	C0	0 N	Firestone FR480 spare P225/70R15 Sidewall cut, 3/32 deep
		Tire Code LR	VN165	8.8.8	25	ST358J	C3	0 N	
KM 60K	VIN [REDACTED]	Tire Code RF	VN208	12.5.12.10	31	ST369J	C0	0 N	One repair Severe tread cuts
		Tire Code LF	VN218	12.11.11	32	ST369J	C0	0 Y	
		Tire Code RR	VN166	8.7.8	30	ST369J	C3	0 N	
		Tire Code LR	VN276	8.8.6	34	ST369J	C3	2 N	
KM 14K	VIN [REDACTED]	Tire Code RF	W2107	12.12.12	25	ST369J	C0	N	One deep tread cut
		Tire Code LF	W2107	12.12.5.13	26	ST369J	C0	N	
		Tire Code RR	W2416	12.12.12	25	ST369J	C0	N	One nail in tread, leaking
		Tire Code LR	W2107	12.12.12	22	ST369J	C0	N	
KM 180K	VIN [REDACTED]	Tire Code RF			30				All four tires 245/70R16 107H General XP2000
		Tire Code LF			29				
		Tire Code RR			29				
		Tire Code LR			32				
KM 112K	VIN [REDACTED]	Tire Code RF			26				All four tires P255/70R16 109S Goodyear Wrangler RT/S
		Tire Code LF			27				
		Tire Code RR			27				
		Tire Code LR			28				
KM 125K	VIN [REDACTED]	Tire Code RF			24				This RF tire well worn to cord. All four tires LT245/75R16 120/116R LR-E General Ameri*550 AS
		Tire Code LF			24				
		Tire Code RR			15				
		Tire Code LR			25				

**REDACTED**

DOT Outside / Middle / Inside

Chip codes C0, C1, C2, C3

ACM Oman Ravindran Service Mgr Ashok Pandey Gen. Mgr		Location Contacts		Ruwi Oman		SH CR=Sholder Cracking		
17 Jun	DATE	DOT	Tread Depth	P	Spec	Chip	R	Comments
KM 14 5	VIN	Tire Code RF	VN368	11,11,11	22	C0	N	TREAD CUTS
	[REDACTED]	Tire Code LF	VN358	12,12,12	25	C0	N	CRACKING -2
	[REDACTED]	Tire Code RR	VN368	12,12,11	24	C1	N	
	[REDACTED]	Tire Code LR	VN368	12,11,12	25	C0	N	2 TREAD CUTS
KM 79K	VIN	Tire Code RF		13,12,12	30			ALL TIRES CFAO89 BRIDGESTONE 265/70 R16
	[REDACTED]	Tire Code LF		11,12,13	29			
	[REDACTED]	Tire Code RR		11,11,11	29			
	[REDACTED]	Tire Code LR		11,12,13	29			
KM 250K	VIN	Tire Code RF	VN386	12,12,12	32	C2	N	Owner stated he has put 16 tires in total on vehicle all Wilderness AT spec Customer said he has had both rear tires blow out two times and tread cam off and has damaged rear tail gate Photos taken Good unit to put Special Service tires on ASAP Drives both on and off road
	[REDACTED]	Tire Code LF	VN358	12,12,12	32	C0	N	
	[REDACTED]	Tire Code RR	W2497	11,10,5,10	31	C2	N	
	[REDACTED]	Tire Code LR	W2497	10,5,10,5,10	32	C2	N	
KM 1K	VIN	Tire Code RF	VN498	13,13,13	25			New Truck
	[REDACTED]	Tire Code LF	VN488	13,13,13	26			
	[REDACTED]	Tire Code RR	VN488	13,13,13	26			
	[REDACTED]	Tire Code LR	VN458	13,13,13	26			
KM 38K	VIN	Tire Code RF			29			Pirelli Scorpion A/T LT245/75 R16 120/116Q LRE
	[REDACTED]	Tire Code LF			28			
	[REDACTED]	Tire Code RR			28			
	[REDACTED]	Tire Code LR			30			
KM 70K	VIN	Tire Code RF	W2347	13,12,10	27	C2	N	Crack 1, missing valve cap, upper side wall cut Crack 1, missing valve cap Crack 1 Crack 1, rubber plug used but is outside of the repair area
	[REDACTED]	Tire Code LF	W2347	11,11,10	30	C1	N	
	[REDACTED]	Tire Code RR	W2347	10,10,10	27	C2	N	
	[REDACTED]	Tire Code LR	W2347	11,11,11	26	C2	Y	
KM 150K	VIN	Tire Code RF			27			Goodyear Wrangler HT LT 245 / 75R16 120 / 116R LRE
	[REDACTED]	Tire Code LF			26			
	[REDACTED]	Tire Code RR			27			
	[REDACTED]	Tire Code LR			28			
KM 25K	VIN	Tire Code RF	W2485	10,10,10	27	C3	N	SH CR 1 SH CR1 SH CR 2 SH CR 2, Cut side wall
	[REDACTED]	Tire Code LF	W2485	10,10,10	28	C3	N	
	[REDACTED]	Tire Code RR	W2485	10,10,10	27	C3	N	
	[REDACTED]	Tire Code LR	W2485		27 ST369J	C3	N	

DOT Outside / Middle / Inside

Chip codes C0 C1 C2 C3

**REDACTED**

KM 36K	VIN [REDACTED]	Tire Code RF	W2037	12.11.11	27	C1	N	SH CR 0
		Tire Code LF	W2037	12.12.12	27	C1	N	SH CR 1
		Tire Code RR	W2087	12.13.12	27	C1	N	SH CR 0
		Tire Code LR	W2087	12.12.12	28	C2	N	SH CR 0
KM 20K	VIN [REDACTED]	Tire Code RF	W2047	12.12.12	28	C1	N	
		Tire Code LF	W2047	11.5.12,12.5	27	C0	N	
		Tire Code RR	W2047	12.12.12	26	C0	N	
		Tire Code LR	W2047	13.12.12	27	C0	N	
KM 42K	VIN [REDACTED]	Tire Code RF	W2406	11.10.10	25	C1	N	SH CR 0, No valve cap
		Tire Code LF	W2168	13.12.5,11.5	28	C0	N	SH CR 0
		Tire Code RR	W2416	10.10.9	22	C1	N	SH CR 0
		Tire Code LR	W2416	11.10.10	23	C0	N	SH CR 0
KM 30K	VIN [REDACTED]	Tire Code RF	W2407	12.11.11	22	C0	N	SH CR 0, No valve cap
		Tire Code LF	W2407	11.11.12	18	C0	N	SH CR 0
		Tire Code RR	W2407	11.11.11	21	C0	N	SH CR 0, No valve cap
		Tire Code LR	W2407	11.11.11	21	C0	N	SH CR 0, No valve cap
KM 55K	VIN [REDACTED]	Tire Code RF	W2476	10.9.10	21	C3	N	SH CR 1
		Tire Code LF	W2117	9.8.8	20	C3	Y	
		Tire Code RR		5.5.6	23	C3	N	Deep crack, Bstone, desert dueler, EJ124
		Tire Code LR	W2416	10.8.5.8	25	C2	Y	Side wall plug, tire is starting to separate, Service Manager advised All tires need to be changed
		Loose Tires W2486, 46KM 1 Cord Repair			7.10.9			Signs of separation starting 70648 Reg No
		VN486 70989 Reg No						Tread BLB Customer had BLB week earlier on other tire

**REDACTED**

DOT Outside / Middle / Inside

Chip codes C0, C1, C2, C3